



# V5816

---

G-PON OLT

*Firmware Release Note*

The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design, are reserved. Technical modifications are possible. Technical specifications and features are binding only in so far as they are specifically and expressly agreed upon in a written contract.

※ Copyright 2021 © DASAN Zhone Solution, Inc.

Issued by Global Technical Assistance Center

## Contents

<b>1</b>	<b><i>Introduction</i></b>	<b>4</b>
1.1	Audience	4
1.2	Release Object	4
<b>2</b>	<b><i>Release Information</i></b>	<b>5</b>
2.1	Documentation	5
2.2	New Feature	5
2.3	List of Fixed Issues	5
2.4	List of Open Issues	6
<b>3</b>	<b><i>Restriction and Dependencies</i></b>	<b>7</b>
3.1	Dependencies	7
3.1.1	Hardware Compatibility	7
3.1.2	BOOT Loader Compatibility	7
3.2	Restriction / Known Problem	7
3.3	Operation Hints	7
<b>4</b>	<b><i>INSTALLATION PROCEDURE</i></b>	<b>8</b>
4.1.	Standard Installation Procedure	8

# 1 Introduction

## 1.1 Audience

This Release Note is intended for V5816 GPON OLT system operators and maintenance personnel for providers of Gigabit passive optical network (G-PON) and Ethernet services. Before installing OLT with new Firmware version, please refer this release note

## 1.2 Release Object

### 1.2.1 Name

- System: V5816
- Release Object: 1.12p1 #0096

### 1.2.2 Release Package Detail

Version name: 1.12p1 #0096

File name: V5816.1.12p1\_0096-01\_88035\_20211201.x

File size: 28,969,764 Bytes

MD5 checksum: ca2133392f57ccb5d2c62d69a99e155a

### 1.2.3 History of Release

Release Date	Firmware Version	Comment
21 <sup>st</sup> AUG 2020	1.04p1 #0080	Official Release
08 <sup>th</sup> DEC 2021	1.12p1 #0096	Official Release

## 2 Release Information

### 2.1 Documentation

For understanding This GPON OLT system, please refer 'Data Sheet'.

### 2.2 New Feature

None

### 2.3 List of Fixed Issues

Salesforce	Title
00069398	V5816: FW 1.04-0050 - ACL can't be removed from MGMT Interface [ANTIK]
00068230	V5816/V5808: FW 1.04 - ARP inspection/arp access-list does not work[TELEFON SERWIS]
00068932	V5808 / V5816 FW 1.04-0050 - How to add privilege to command "quota" to user ?
00079131	V5808/V5816: FW 1.04p1-0080 â€“ Process gpon_oltd has been crashed (#315369)
00078548	V5816 FW 1.04p1 - sleGponOnuPortAdminStatus - SNMP returns wrong value
00080575	V5808/V5816: FW 1.04p1-0080 - Can't login with Radius account if secondary IP is on vlan interface
00078950	V5808 FW 1.04p2-0088 - Can't login to the OLT using ssh key pair. Login incorrect.
00080892	V5808/V5816: FW 1.04p1-0080 - Lack of hostmane field in remote syslog packet. Clients want to identify OLT by hostname, not by IP address
00078309	V5816 FW 1.04p1-0080 - DHCPv6 option 37 and 18
00081491	V5808/V5816: FW 1.11 #0086 - Can't choose the ssh port using ssh client on the OLT (all Dasan OLTs)
00083093	V5808/V5816: FW 1.12-0094 – DHCPv6 Relay L2 function according to RFC6221
00083064	V5808/V5816: FW 1.12-0094 – Wrong behaviour of policy replace for IPv6 DHCP Snooping

---

## 2.4 List of Open Issues

None

---

## 3 Restriction and Dependencies

### 3.1 Dependencies

#### 3.1.1 Hardware Compatibility

Please refer "Product Data Sheet"

#### 3.1.2 BOOT Loader Compatibility

This version of software is compatible with the following Boot Loader Version:

- Boot Loader Version: 01.72.0002

### 3.2 Restriction / Known Problem

None

### 3.3 Operation Hints

None

---

## 4 INSTALLATION PROCEDURE

### 4.1. Standard Installation Procedure

For the safety GPON ONT operation and firmware upgrade, please refer to 'GPON OLT User Manual'.